

REPAIR PARTS

LABORATORY PRODUCTS & DRENCH HOSES

SE-570, SE-571, SE-572, SE-573, SE-575, SE-568

| PART # | PRICE | PRODUCT DESCRIPTION |
|------------|-----------|---|
| RPG05-0673 | \$ 15.00 | Internal o-rings, screws for valve |
| RPG05-0686 | \$ 29.70 | Valve repair group (SE-570) |
| RPG05-0714 | \$ 67.10 | Bullhorn assembly with aerated sprays |
| RPG05-1177 | \$ 86.80 | Aerator replacement group (6 each) |
| RPG07-0104 | \$ 52.90 | Flip top cap replacements (20 per bag) |
| RPG20-1996 | \$ 141.10 | Ball valve assembly (SE-572) |
| RPG20-2015 | \$ 520.00 | Swing down eyewash valve assembly |
| RPG38-0379 | \$ 66.60 | Spray head assembly with aerators (4 per bag) |
| RPG38-0421 | \$ 150.00 | Non-aerated spray head assembly |

DRENCH HOSES

| PART # | PRICE | PRODUCT DESCRIPTION |
|-------------|-----------|--|
| G20-0584-PC | \$ 134.60 | Drench hose self closing valve repair group (SE-920) |
| RPG05-1177 | \$ 86.80 | Aerator replacement group (6 each) |
| RPG07-0104 | \$ 61.30 | Non-aerated spray head assembly (4 per bag) |
| RPG20-1742 | \$ 153.60 | Drench hose stay open valve repair group (SE-927) |
| RPG38-0379 | \$ 66.60 | Aerated spray head assembly for SE-580/582 (4 each) |
| RPG38-0390 | \$ 52.90 | Flip top cap replacements (20 per bag) |

IMAGES



RPG20-1996



RPG05-0673



RPG20-2015



RPG38-0421



RPG38-0379



RPG05-1177



RPG07-0104



G20-0584-PC



RPG05-0714



RPG05-1177



RPG20-1742



RPG05-0686