

# REPAIR PARTS

## TRADITIONAL SERIES EYEWASHES

### SE-580 TRADITIONAL SERIES AERATED

PART #	PRICE	PRODUCT DESCRIPTION
SE-910	\$ 120.00	1/2" Ball valve assembly
SE-910-SS	\$ 285.00	1/2" Stainless steel ball valve assembly
RPG05-0814	\$ 32.20	Bullhorn washer group
RPG05-0714	\$ 67.10	Aerated bullhorn assembly with spray heads for SE-580/582
RPG05-1177	\$ 86.80	Aerator replacement group (6 each)
RPG38-0379	\$ 66.60	Aerated spray head assembly for SE-580/582 (4 each)
RPG07-0104	\$ 52.90	Flip top cap replacements (20 per bag)

## IMAGES

